

Tests:

S. E. Farrar, Sr., Clerk

1912.

PLAT BOOK # 4, PAGE # 48

2010  
 13° 54'  
 135° 16.3  
 140° 47'  
 320° 04'  
 140° 37.4  
 319.8

2.  
12.92 Ac.

Gordon Clayton

Buggy Hole  
 553° 36' E  
 311.78  
 553° 42' E  
 489.8

3.  
6.46 Ac.

4.  
6.46 Ac.

153° 22' W  
 937.1  
 N34° 30' W  
 234.4  
 N59° 15' W  
 132.0  
 N24° 24' E  
 132.0  
 N37° 58' W  
 197.9  
 N49° 06' W  
 260.0  
 N36° 27' E  
 270.2  
 3/4" I. Pipe (found)

Key, No. 785  
inia

Allen

Milton Parcel

(13C)

(13D)

3/4" I. Pipe (found)

1/2" Iron Pipe  
 1128.8  
 286  
 1/2" Iron Pipe  
 353.3  
 1/2" Iron Pipe (found)

1/2" I. Pipe (lost)  
 N53° 22' W  
 106.5  
 Iron Jkt (found)

522° 54' W  
 742° 54' E  
 523.8  
 523.8

3/4" I. Pipe (found)  
 (374.2)  
 N53° 59' W  
 (350.0)  
 724.9

